



Case Study

application Railway Reinforcement
location Scotford, Alberta
product Mirafi® RS580i and H2Ri

job owner
engineer
date of installation

Canadian Pacific Railway (CP)
Clifton Associates
2016

At Canadian Pacific Railway (CP), when it comes to safety, there is always a mandate to improve. That mandate can be boiled down to the words of CEO, Hunter Harrison: "Don't get anybody hurt. Because -- regardless of a railroad's safety numbers or ranking -- even one derailment, injury or fatality is one too many." CP has long been an industry leader in rail safety and are more focused on it than ever by committing to protect their people, their communities, their environment and their customers' goods.

Canadian Pacific Railways' continued investment in their infrastructure in recent years helped make CP the safest Class I railroad in North America for the last 10 years. CP continues to invest in its network to enhance safety, improve efficiency, create velocity, and provide the best service possible to customers.

CP's continuous rail maintenance and safety program identified a section of track on the Scotford Subdivision, northeast of Edmonton, Alberta that was subject to track settlement resulting in cross level variations. CP implemented a 10 mph speed restriction on the section of track and scheduled it for immediate repair.



Unrepaired track section with cross level variation due to settlement issues.

Clifton Associates, a leading Western Canadian geotechnical engineering firm with expertise in railway infrastructure, was brought on board by CP to investigate potential causes and prescribe a repair. Field investigations showed that a significant amount of moisture was present in the subgrade and surrounding area. Signs of mud-pumping (movement of subgrade material into the coarse ballast) were apparent along the track surface, indicating that the wet conditions were accentuating the process of subgrade attrition and that the sub-ballast was no longer performing as originally intended.

According to the authors, Selig and Waters of "Track Geotechnology and Substructure Management", the primary functions of the sub-ballast include:

1. Helping to reduce stresses to subgrade.
2. Protect the subgrade from freezing.
3. Act as a separator between the ballast and the sub-ballast.
4. Prevent upward subgrade fines migration.
5. Prevent subgrade attrition by ballast.
6. Shed water above.
7. Drain the water below.

CP and Clifton Associates had successfully used a combination of nonwoven geotextile, triangular geogrid, and cellular confinement products to rehabilitate similar sections of rail.



Evidence of mud pumping and ballast contamination prior to repair.

The railway was interested in options that would continue to reduce ballast/sub-ballast requirements, protect the ballast from fouling long term, and assist with protection against frost heave and high moisture content subgrades. Both parties had read about the performance of TenCate Mirafi® RS580i high strength woven geosynthetic in other third party studies/projects and reached out to TenCate Geosynthetics for a proposal.

TenCate performed AREMA analyses using the Talbot equation for various subgrade conditions. The options provided to CP and Clifton Associates included single layer (1 layer of geosynthetic between the sub-ballast and subgrade) and double layer (1 layer of geosynthetic at the sub-ballast/subgrade interface and a second layer at the sub-ballast/ballast interface.) dependent upon the results of a geotechnical investigation and determination of the subgrade strength.

Due to the urgent nature of the repair, CP ultimately decided to select the TenCate solution for the assumed worst case subgrade condition which incorporated Mirafi® H₂Ri wicking geosynthetic at the subgrade and Mirafi® RS580i at the sub-ballast/ballast interface. Generally, the weaker the subgrade, the more benefit the geosynthetic provides.

Another important factor in the decision to try the TenCate solution was to decrease track down time. In this instance, the inclusion of the 2 layers of Mirafi® geosynthetic resulted in a 43% reduction in the amount of ballast and sub-ballast required which would also correspond to a significant savings in time related to placement, spreading, and compaction.

Repair of the first 22 meter-long section was completed in just under 7 hours. Removal of the track panel and excavation/removal of the existing rail embankment was completed in approximately 1 hour. Mirafi® H₂Ri was placed on the prepared subgrade, backfilled with sub-ballast, and compacted in under 90 minutes. The sequence of events from this point onward was placement of the Mirafi® RS580i, reconnection of the track panel, ballast placement, ballast compaction and grade correction with the regulator; Placement of the geosynthetic was a minimal amount of the 4 hours required to perform these last steps.



Track panel is removed.



Contaminated rail ballast: The dark material is topsoil that has migrated into ballast. The lighter area is sub-ballast, which has migrated into ballast.



Ballast contamination and moisture enough to support plants and root systems.



Mirafi® H2Ri installed at the subgrade/subballast interface.



Mirafi® RS580i installed at the ballast/sub-ballast interface.



Reconnecting the track panel.



Placing new ballast.



Placing new ballast.



Lifting rail and compaction of ballast under rail ties.

CP will be monitoring the track performance on the repaired subgrade over the next few years. The expectation is that they will know the level of performance after the first Spring freeze, when the subgrade is expected to have the maximum moisture content.



Installation complete.

TenCate Geosynthetics Americas assumes no liability for the accuracy or completeness of this information or for the ultimate use by the purchaser. TenCate Geosynthetics Americas disclaims any and all express, implied, or statutory standards, warranties or guarantees, including without limitation any implied warranty as to merchantability or fitness for a particular purpose or arising from a course of dealing or usage of trade as to any equipment, materials, or information furnished herewith. This document should not be construed as engineering advice.

Mirafi® is a registered trademark of Nicolon Corporation..

© 2016 TenCate Geosynthetics Americas

1116

365 South Holland Drive Tel 800 685 9990 Fax 706 693 4400
Pendergrass, GA 30567 Tel 706 693 2226 www.mirafi.com



TENCATE
materials that make a difference