



RAILWAY PROJECT PROFILE

Kansas City Southern, Ciudad Valles, Tamaulipas, Mexico **Solution: Mirafi® RS380i**

- ✂ Existing track had issues with ballast fouling/mud-pumping, weak subgrade deformed which resulted in cross elevation variations and tie failures, and reduction in load capacity.
- ✂ Investigation found both expansive and collapsible foundation soils.
- ✂ TenCate recommended Mirafi® RS380i to provide separation, filtration, reinforcement, and confinement of the sub-ballast.